Inspection Report

Name of Work	:	Construction of 2nd Floor Samudaya Bhavana at Maruthinagara in ward no. 08 (Kodigehalli) Kodigehalli sub division
Work Order	:	EE/BTP/BBMP/E-TND/98/2013-14 Dated: 26.07.2013.
Agency	:	M.B. Hombal
B.R. No & Date	:	397/2014-15 Dated: 29.11.2014
Bill Amount	:	18,85,470/-
Job Code	:	008-11-000053
P. Code	:	P-1878
Date of Inspection	:	16-03-2016

The above said work was shown to me by the Concerned Ward Engineer.

Then work is inspected by me along with the Concerned Ward Engineer Smt Srinivas and it was done at Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: **Inspection report for the Work: Construction of 2nd Floor Samudaya Bhavana at Maruthinagara in Ward No.08 (Kodigehalli), Kodigehalli Sub Division**



MANJUNATH. K
DGM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGI... (ADTD)

PUBLIC WORKS DEPARTMENT

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (
PUBLIC WORKS DEPART

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)